

Monitoring Data Record

Project Title: Twin Oaks (R-2302) COE Action ID: 199920857
 Stream Name: Perennial stream flowing into the New River DWQ Number: 990491
 City, County and other Location Information: Sta. 39+50 – 48+50 on US 21 S of Twin Oaks
 Date Construction Completed: N/A Monitoring Year: (1) of 1
 Ecoregion: _____ 8 digit HUC unit 05050001
 USGS Quad Name and Coordinates: _____

Rosgen Classification: _____

Length of Project: 1334' Urban or Rural: Rural Watershed Size: _____

Monitoring DATA collected by: K. Smith, J. Elliott, M. Green Date: 5/19/04

Applicant Information:

Name: NCDOT Roadside Environmental Unit

Address: 1 S Wilmington St. Raleigh, NC 27611

Telephone Number: (919) 733-2920 Email address: _____

Consultant Information:

Name: _____

Address: _____

Telephone Number: _____ Email address: _____

Project Status: Complete

Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.): Level (1) 2 3

Monitoring Level 1 requires completion of *Section 1, Section 2 and Section 3*

Permit States: NCDOT shall visually monitor the vegetative plantings and insure complete stabilization of the stream. This monitoring shall include visual monitoring of planted vegetation quarterly for a minimum of one year after final planting.

Section 1. PHOTO REFERENCE SITES

(Monitoring at all levels must complete this section)

Attach site map showing the location and angle of all reference photos with a site designation (name, number, letter, etc.) assigned to each reference photo location. Photos should be provided for all structures and cross section locations, should show both banks and include an upstream and downstream view. Photos taken to document physical stability should be taken in winter. Photos taken to document vegetation should be taken in summer (at representative locations). Attach photos and a description of each reference photo or location. We recommend the use of a photo identification board in each photo to identify location.

Total number of reference photo locations at this site: 4 reference points, 2 photos at each

Dates reference photos have been taken at this site: 12/08/03, 5/19/04

Individual from whom additional photos can be obtained (name, address, phone): _____

Other Information relative to site photo reference: _____

If required to complete Level 3 monitoring only stop here; otherwise, complete section 2.

Section 2. PLANT SURVIVAL

Attach plan sheet indicating reference photos.

Identify specific problem areas (missing, stressed, damaged or dead plantings):

Estimated causes, and proposed/required remedial action:

ADDITIONAL COMMENTS: No problems at this time. Stream is highly vegetated with various thick grasses. Trees are doing well; 2' – 4' in height.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The stream is very stable and is doing well. There is some severe hillside erosion above the silt fence away from the stream near STA 40. However erosion has not altered the stream at this time. The division maintenance forces are meeting on June 2, 2004 to determine what repairs are to be made. After the June 2, 2004 meeting, it was determined that additional springheads had developed under the toe of the fill, which caused the destabilization. Alleghany County Maintenance is going to immediately install temporary erosion control measures and a purchase order contract will be issued by the District to make the repairs.

Date Inspected	Station Number	Station Number	Station Number	Station Number	Station Number
Structure Type	STA. 40				
Is water piping through or around structure?					
Head cut or down cut present?					
Bank or scour erosion present?	Hillside erosion above the silt fence.				
Other problems noted?					

NOTE: Attach separate narrative sheets to each monitoring report describing/discussing the overall monitoring results. Include the identification of specific problem areas/channel failures, estimated cause and proposed/required remedial action. This should include a brief discussion of any parameter that has changed significantly from as-built.

Twin Oaks



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5
2nd Quarter - May 2004



Photo 6

Twin Oaks



Photo 7



Photo 8